

## **Ferno 35X Ambulance Cot Field Inspection**

- Ferno is conducting a field inspection on a limited range of Model 35X ambulance cots.
- ONLY 35X PROFlexX Cot Customers with Serial Numbers between 06 002156 and 07 054091 (manufactured between January 17, 2006 and August 16, 2007) need to inspect their cots and contact Ferno Technical Support at 866-987-3776 or [quality.products@ferno.com](mailto:quality.products@ferno.com).
- Current Ferno Model 35X production units are not affected and no further action is required.

*Ferno stands by its products along with the quality of engineering and manufacturing that goes into every product. We thank you for your confidence and support.*